

# Liquid Flow Indicators

## Flow Indicators

Part Number	Pipe Size	Back Check	Manufacturer
<b>G201-10</b>	1 1/4" FNPT	Yes	Fisher
<b>G201-16</b>	2" FNPT	Yes	Fisher
<b>G201-24</b>	3" FNPT	Yes	Fisher
<b>FC150</b>	1 1/2" FNPT	Yes	Corken
<b>FC200</b>	2" FNPT	Yes	Corken
<b>FC300</b>	3" FNPT	Yes	Corken
<b>ME875S-16</b>	2" FNPT	Yes	Marshall Excelsior
<b>ME875S-24</b>	3" FNPT	Yes	Marshall Excelsior
<b>5520-2</b>	2" MPT 2" Tee Needed	No	Squibb Taylor
<b>5520-3</b>	3" MPT 3" Tee Needed	No	Squibb Taylor



G200-16



ME875S-16

Bergquist



FC200

## FLOW INDICATOR REPAIR PARTS

### Flow Indicator Repair Parts

bergquistinc.com | 800 537 7518

Part Number	Repairs Valve	Comment
<b>5520</b>	5520-2, 5520-3	Dial Only
<b>Individual</b>	G201 Series	Contact Us
<b>FC125 Kit</b>	FC150	Tool 3432 Needed For Repair
<b>FC200 Kit</b>	FC 200, FC300	



5520-2

## BALL CONE CHECK VALVES

Materials of Construction  
 Body - cast bronze, LP only  
 Tail Piece - brass rod  
 Ball Check - glass filled TFE Teflon  
 Guide - brass rod  
 Spring - 300 Series stainless steel

Part No.	Size
<b>61-102</b>	3/8" FNPT
<b>61-103</b>	1/2" FNPT
<b>61-104</b>	3/4" FNPT
<b>61-105</b>	1" FNPT
<b>61-106</b>	1 1/4" FNPT
<b>61-107</b>	1 1/2" FNPT
<b>61-108</b>	2" FNPT



"Apollo"

61-105